

Technical datasheet

NORM Monitor

Introduction

The NORM monitor measures alfa, beta and gamma rays. CPS (Counts Per Second) are measured as a unit depending of the sensitivity of the measure meter.

The NORM monitor is stored in the associated trunk for protection when not in use.

OTS item number.: 9000-487



Features

- Battery operated monitor
- Versatile use
- Accurate measure
- Ease of operation
- Lightweight

Capacity & performance

Measure range:	0-4.000 CPS
Measurement uncertainties:	+/- 20 %

Safety features

- Outer case is chemically inert
- High tolerance to wet conditions
- Suitable for use in oil & gas industries

Weight & dimensions

Gross Weight:	